DART AEROSPACE LTD	Work Order:	24665
Description: Qeturn 423	Part Number:	03195/03197
Dwg:	Qty:	2
		Page of

Step	Location	Procedure	Ву	Date	Qty	
1	DC	Issue Traveler				
1	QC4is	Inspect parts for completness	1	05-10-25	2	1
	*	and damage				
2	FP	Touch up 2x 103197-041 bars grey	W	05 10 db	1	
		AS per RS 1004 QS1005 Ref (4.3.5.6)				
3	KP	Place the following into stock				
		aty P/N Desc. Batch#				
	·	2 03195-043 bracket \$22178-				
		2 03195-041 bracket B22178				
		2 03268-1 Placard B22602				
		4 AN4-13A bolt \$16114	1	05-10-27		1
4	KP	discard remainder of used hardware :				
		2 ms 24694-5152 screw m15057		•		
5	QC3	Inspect touch up on D3197-041	CL.	5/10/27	2	
6	K P	4.10(-1)	1	05/10/27	2	
		identified with batch number B24665,				
		PATO Kit: 24162 0412-702-023				
7	QC4	Inspect work to step 6				
8	AC		Sac	05./0-28	772	
q		close w/o		05/10/28		

Rev	Date	Change	Revised By	Approved